

2022 Electronic Systems Product Catalog

| Product Name | Part Number |
|---|----------------|
| Model 527™ Radar Signal Simulator (w/ MMW) NSN 6940-01-563-1116 | 39300-40002-10 |
| Model 527 with MMW and PRTS™ Adaptable | 39300-40002-20 |
| Model 527 without MMW | 39300-40002-30 |
| Model 527 without MMW and PRTS Adaptable | 39300-40002-40 |
| Model 527 without MMW and HHDU | 39300-40002-50 |
| Laboratory Model 527 (Front) | 40504-40000-10 |
| Laboratory Model 527 (Rear) | 40504-40000-20 |
| Laboratory Model 527 (PRTS) | 40504-40000-30 |
| Model 527 Calibrations (CONUS locations) | |
| Model 527 Calibrations (OCONUS locations) | |
| Model 527 Calibration Kit | 39300-41010-10 |
| Model 527 Training Course (2 day) CONUS | |
| | |
| Portable Range Threat Simulator (PRTS) | 77155-40000-10 |
| High Power Portable Range Threat Simulator (HPRTS™) | 77155-40100-10 |
| Integrated Tester for Aircraft Survivability Systems (ITASS™) | 40514-40000-10 |
| ITASS TPG | 40514-40050-10 |
| ITASS Training Course (3-day) CONUS | |
| | |
| Joint Service Electronic Combat Systems Tester (JSECST™) AN/USM-670A NSN 4920-01-618-5101 KV | 40469-40001-20 |
| Laboratory JSECST NSN 6940-01-619-8416 KV | 40469-41000-10 |
| | |
| Man-Portable Aircraft Survivability Trainer (MAST™) (No Laser) | 40390-40002-40 |
| MAST Laser | 22768-001 |
| RF SW/Freq Dist Unit (RFSU) | 154050-002 |
| RF SW/Freq Dist Unit (RFSU) | 152750-002 |
| Calibration Kit, Verification | 125670-002 |
| RFIU | 125610 |
| RFIU Enhanced | 125610-002 |
| | |
| VXI RF Source Model Number VXI SSI-10 | 40407-40008-10 |

TEXTRON Systems

WWW.TEXTRONSYSYSTEMS.COM

| Product Name | Part Number |
|---|-----------------|
| VXI Reference Oscillator Assembly Model Number VXI ROA-10 | 40407-40013-10 |
| RFS340 | 40498-40100-10 |
| 500 MHz Source Assv Oscillator (LXI Oscillator) | 40498-40150-10 |
| RF Stimulus Unit | 39196-40200-10 |
| RF Measurement Unit | 39196-40300-10 |
| RFIU Power Supply | 39196-40400-10 |
| Intermediate Frequency Interface Unit (IFIU) | 39196-40600-10 |
| SASI-240 | 40452-42100-10 |
| SASI- RF Module Assembly | 40452-42105-10 |
| SASI Front Panel Assembly | 40452-42121-10 |
| SASI Digital Interface Unit | 40452-42150-10 |
| RF Module Assembly | 40563-40020-10 |
| Processor CCA | 40568-47010-10 |
| eCASS Repairs | |
| RF Stimulus Unit Repair | 39196-40200-10 |
| RF Measurement Unit Repair | 39196-40300-10 |
| RFIU Power Supply Repair | 39196-40400-10 |
| IFIU Repair | 39196-40600-10 |
| SASI-240 Repair | 40452-42100-10 |
| LXI Oscillator Repair | 40498-40150-10 |
| LXI Repair | 40498-40100-10 |
| Synthetic Stimulus Instrument (SSI) Model Number VME SSI-40 | 40354-41110-40 |
| Synthetic Stimulus Instrument (SSI)* Model Number VME SSI-50 | 40354-41110-50 |
| Synthetic Stimulus Instrument (-150 SSI)* With MMw | 40491-40000-150 |
| Synthetic Stimulus Instrument (-150 SSI)* Without MMw | 40491-41000-150 |
| Synthetic Stimulus Instrument (-150 SSI)* With MMw | 40491-42000-150 |
| Synthetic Stimulus Instrument (-150 SSI)* Without MMw | 40491-43000-150 |
| Synthetic Stimulus Instrument (-151 SSI)* With MMw | 40491-40000-151 |
| Synthetic Stimulus Instrument (-151 SSI)* Without MMw | 40491-41000-151 |
| Synthetic Stimulus Instrument (-151 SSI)* With MMw | 40491-42000-151 |

TEXTRON Systems

WWW.TEXTRONSYSYSTEMS.COM

| Product Name | Part Number |
|---|-----------------|
| Synthetic Stimulus Instrument (-151 SSI)* Without MMw | 40491-43000-151 |
| Millimeter Wave (MMw) RF Hardware Assembly Model Number VME MMW-10 | 40354-41155-10 |
| Stimulus Cabinet* | 40354-41105-50 |
| Stimulus Cabinet (-150)* | 40354-41105-150 |
| Maintenance/Alignment Receiver Cabinet* | 40354-41100-50 |
| Maintenance/Alignment Receiver Cabinet (-150)* | 40354-41100-150 |
| Integrated EW Cabinet Assembly* <i>(Used in our Single Cabinet EW Simulator, P/N 40354-40150-10)</i> | 40354-40151-10 |
| Integrated EW Cabinet Assembly (-150)* <i>(Used in our Single Cabinet EW Simulator, P/N 40354-40150-110)</i> | 40354-40151-110 |
| Integrated EW Cabinet Assembly* <i>(Used in our Single Cabinet EW Simulator, P/N 40354-40150-20)</i> | 40354-40151-20 |
| Integrated EW Cabinet Assembly (-150)* <i>(Used in our Single Cabinet EW Simulator, P/N 40354-40150-120)</i> | 40354-40151-120 |
| Stimulation Electronics Assembly | 40354-40220-20 |
| Stimulation Electronics Assembly (-150) | 40537-41100-10 |
| Mini A ² PATS® (Empty Cabinet) | |
| Mini A ² PATS (1 SSI) | 40354-40320-10 |
| Mini A ² PATS -150 (1 SSI) | 40354-40320-110 |
| Mini A ² PATS -150 (1 MMw SSI) | 40354-40320-210 |
| Mini A ² PATS (2 SSIs) | 40354-40320-20 |
| Mini A ² PATS -150 (2 SSIs) | 40354-40320-120 |
| Mini A ² PATS -150 (2 MMw SSIs) | 40354-40320-220 |
| Mini A ² PATS (3 SSIs) | 40354-40320-30 |
| Mini A ² PATS -150 (3 SSIs) | 40354-40320-130 |
| Mini A ² PATS -150 (3 MMw SSIs) | 40354-40320-230 |
| Mini A ² PATS (4 SSIs) | 40354-40320-40 |
| Mini A ² PATS -150 (4 SSIs) | 40354-40320-140 |
| Mini A ² PATS -150 (4 MMw SSIs) | 40354-40320-240 |
| Mini A ² PATS (5 SSIs) | 40354-40320-50 |
| Mini A ² PATS -150 (5 SSIs) | 40354-40320-150 |
| Mini A ² PATS -150 (5 MMw SSIs) | 40354-40320-250 |
| Mini A ² PATS (6 SSIs) | 40354-40320-60 |
| Mini A ² PATS -150 (6 SSIs) | 40354-40320-160 |

TEXTRON Systems

WWW.TEXTRONSYSYSTEMS.COM

| Product Name | Part Number |
|---|----------------------------------|
| Mini A ² PATS -150 (6 MMw SSIs) | 40354-40320-260 |
| Mini A ² PATS (7 SSIs) | 40354-40320-70 |
| Mini A ² PATS -150 (7 SSIs) | 40354-40320-170 |
| Mini A ² PATS -150 (7 MMw SSIs) | 40354-40320-270 |
| Mini A ² PATS (8 SSIs) | 40354-40320-80 |
| Mini A ² PATS -150 (8 SSIs) | 40354-40320-180 |
| Mini A ² PATS -150 (8 MMw SSIs) | 40354-40320-280 |
| A2 Desktop Signal Generator (A ² DSG™), Host | 40530-40000-9099 |
| A2 Desktop Signal Generator (A ² DSG), Host -150 | 40530-40010-9099 |
| A2 Desktop Signal Generator (A ² DSG), H+1 SSI | 40530-40000-1099 |
| A2 Desktop Signal Generator (A ² DSG), H+1 SSI -150 | 40530-40010-1099 |
| A2 Desktop Signal Generator (A ² DSG), H+1 MMw SSI -150 | 40530-40020-1099 |
| A2 Desktop Signal Generator (A ² DSG), H+2 SSIs | 40530-40000-2099 |
| A2 Desktop Signal Generator (A ² DSG), H+2 SSIs -150 | 40530-40010-2099 |
| A2 Desktop Signal Generator (A ² DSG), H+2 MMw SSIs -150 | 40530-40020-2099 |
| A2 Desktop Recorder/Injector (A ² DRI™) 2 channel | 40520-41000-20 |
| A2 Desktop Recorder/Injector (A ² DRI) 4 channel | 40520-41000-40 |
| A ² PATS DGEN Interface Kit | 40520-40105 |
| RF Switch Matrix | 40354-40500-10 |
| RF Switch Matrix -150 | 40354-40500-110 |
| A ² PATS Simulation Control Software | 40535-41025-10 40536-70001-10 |
| A ² PATS Emulator | 40536-40035-10 |
| A ² PATS Installation | |
| A ² PATS 4-day Training Course | |
| A²PATS Spares Pricing | |
| Stimulus Cabinet Spares Kit | 40354-40246-20 |
| Stimulus Cabinet Spares Kit -150 | 40354-40246-120 |
| Maintenance/Alignment Receiver Cabinet Spares Kit | 40354-40246-10 |
| Maintenance/Alignment Receiver Cabinet Spares Kit -150 | 40354-40246-110 |
| Integrated EW Cabinet Assembly Spares Kit | 40354-40246-40 |
| Integrated EW Cabinet Assembly Spares Kit - 150 | 40354-40246-140 |

TEXTRON Systems

WWW.TEXTRONSYSTEMS.COM

| Product Name | Part Number |
|--|---|
| Mini-A ² PATS Spares | 40354-40246-30 |
| Mini-A ² PATS Spares – 150 | 40354-40246-130 |
| A ² PATS Workstation, SIMENGINE | 40536-41020-10, -20, -30, -50, -60, & -70 |
| A ² PATS Workstation, SIMUI | 40536-41025-10 |
| Alignment Processor Assembly | 40354-40013-10 |
| Alignment Receiver Assembly | 40354-40310-10 |
| Alignment Receiver Assembly | 40354-40310-20 |
| CCA, ALI Proc MB | 40354-47013-10 |
| CCA, RFC/AP/CHRP RTM | 40354-47023-20 |
| CCA, RS Processor | 40354-47011-10 |
| CCA, SC CTR TRAN MOD | 40354-47021-10 |
| CCA, STIM CTL | 40354-47210-10 |
| CCA, Sync-Trigger | 40354-47050-20 |
| Kit, Sys Mon Retrofit Maint | 40501-47094-10 |
| Kit, Sys Mon Retrofit Stim | 40501-41095-10 |
| PDU, Single Phase | 40533-90100-1 |
| PDU, Three Phase | 40533-90300-1 |
| Runtime Sim Assy | 40354-40135-10 |
| Stim Ctl Assy | 40354-40115-10 |
| VME Processor Assy | 40536-40045-10 |
| A²PATS® Repairs | |
| -50 SSI Minor Repair | 40354-41110-50 |
| -150 SSI without MMW Minor Repair | 40491-41000-150 |
| -150 SSI with MMW Minor Repair | 40491-40000-150 |
| -151 SSI without MMW Minor Repair | 40491-41000-151 |
| -151 SSI with MMW Minor Repair | 40491-40000-151 |
| -50 SSI Major Repair | 40354-41110-50 |
| -150 SSI without MMW Major Repair | 40491-41000-150 |
| -150 SSI with MMW Major Repair | 40491-40000-150 |
| -151 SSI without MMW Major Repair | 40491-41000-151 |
| -151 SSI with MMW Major Repair | 40491-40000-151 |
| A²PATS Upgrade Kits | |
| Stim Enclosure 4.4 Upgrade Kit | 78231-10014-10 |
| Stim Cabinet 4.4 Upgrade Kit | 78231-10012-10 |
| Maintenance Cabinet 4.4 Upgrade Kit | 78231-10011-10 |
| Stim Cabinet MMW Upgrade Kit | 40537-40520-20 |

TEXTRON Systems

WWW.TEXTRONSYSYSTEMS.COM

| Product Name | Part Number |
|---|-----------------------------|
| Maintenance Cabinet MMW Upgrade Kit | 40534-40201-20 |
| Maintenance Enclosure MMW Kit | 78231-10013-10 |
| Stim Cabinet -150 Power Upgrade Kit | 78231-10030-10 |
| Maintenance Cabinet -150 Power Upgrade Kit | 40536-40510-410 |
| A2 Desktop Signal Generator (A ² DSG), Upgrade Kit | 40530-40301-12099 |
| WaveCore™ TRM Test Platform TRM 26 GHz Configuration | A9026-41000-00 |
| WaveCore PTS Test Platform PTS 40GHz Configuration | A8040-41000-00 |
| WaveCore ADT Test Platform ADT Base System | A7000-41000-00 |
| Interface Controller II (IFC II) (Priced in conjunction with WaveCore system purchase) | A9000-42002-10 |
| C23-EWO Software License | 50301-70029-1 |
| ABE® Model 310A (Green) NSN 4920-01-575-4554 | 40262-44000-30 |
| ABE Model 310A (White) NSN 4920-01-540-4173 | 40262-44000-40 |
| ABE Model 410A (Green) | 40262-44000-50 |
| ABE Model 410A (White) | 40262-44000-60 |
| ABE Eurofighter Harmonization Kit AGE | 37857-00002-10, 20,30 |
| ABE Eurofighter Harmonization Kit WSTGE | 37857-00001-10 |
| ABE Eurofighter Harmonization Kit AGE w/EScan Radar Adapter | 37857-00004-10, 20,30,40 |
| ABE Model 300 | 40262-40000-10 |
| ABE Model 310 (Green) | 40262-44000-10 |
| ABE Model 310A (Green) | 40262-44000-30 |
| ABE Model 310A (White) | 40262-44000-40 |
| ABE Model 410A (Green) | 40262-44000-50 |
| ABE Model 410A (White) | 40262-44000-60 |

TEXTRON Systems

WWW.TEXTRONSYSTEMS.COM

| Product Name | Part Number |
|---|------------------------------------|
| ABE Model 300 for WSTGE | 37857-40010-10 |
| ABE Model 300 for AGE | 37857-40060-10 |
| ABE Model 310A for AGE/WSTGE | 37857-40080-10, 20,30 |
| ABE® Adapter Set Calibration Pricing: | |
| AC-130H | 38808-40000-10 |
| AC-130U | 39358-40400-10 |
| AC-130W | 71253-40020-10 / 71253-40030-10 |
| AH-1W | 38413-40000-10 |
| AH-1Z (customer part number 3239AS850-1) | - |
| Apache AMASE | 38976-40000-10 |
| Apache Factory/Depot | 40262-41005-10/ 40262-41400-10 |
| Apache Field | 40262-41401-10 |
| AV-8B | 39188-40000-10 |
| C-17 ADL (customer part number 17G570767-1) | - |
| C-17 IRU (customer part number 17G570765-1) | - |
| C-17 LAIRCM | 38465-40000-10/ 38465-10000-10 |
| C-17 SKE (customer part number 17P1U5015-1) | - |
| C-130 AMP | 38596-40000-10 |
| CH-47F | 39659-40000-10 |
| CH-47F Pod Mount | 39659-40020-10 |
| Eurofighter AGE | 37857-40040-10 |
| Eurofighter WSTGE | 37857-40000-10 |
| Eurofighter e-SCAN Radar | 37857-40500-10 |
| HH-60G Adapter Set | 39815-40000-10 |
| HH-60G EGI Kit | 39815-40020-10 |
| Joint Strike Fighter - Common (customer part number 2SJJ02894-0002) | 38461-40070-10 |
| Joint Strike Fighter - CTOL/CV (customer part number 2SJJ02907-0003) | 38461-40050-10 |
| Joint Strike Fighter - CTOL Peculiar (customer part number 2SJJ02902-0003) | 38461-40080-10 |

TEXTRON Systems

WWW.TEXTRONSYSYSTEMS.COM

| Product Name | Part Number |
|--|-----------------------------------|
| Joint Strike Fighter - CV Peculiar (customer part number 2SJJ02906-0003) | 38461-40085-10 |
| Joint Strike Fighter - Factory (customer part number 2SJJ02893-0003) | 38461-40096-10 |
| Joint Strike Fighter - FCAM (customer part number 2SJJ00966-0001) | 38461-40041-10 |
| Joint Strike Fighter - Internal Gun Mount (customer part number 2SJJ02903-0001) | 38461-40055-10/ 38461-40056-10 |
| Joint Strike Fighter - Missionized Gun (customer part number 2SJJ02899-0001) | 38461-40076-10 |
| Joint Strike Fighter - STOVL (customer part number 2SJJ02898-0003) | 38461-40040-10 |
| Joint Strike Fighter - STOVL Peculiar (customer part number 2SJJ02897-0003) | 38461-40075-10 |
| Joint Strike Fighter Adapter Evaluation Fee | |
| MH-47G | 39419-40050-10 |
| MH-60/MH-47G Common | 39419-40040-10 |
| MH-60/MH-47G MMR | 39419-40012-10 |
| MH-60L | 39419-40008-10 |
| MH-60M CAAS Assault | 39419-40060-10 |
| MH-60M CAAS OAP | 39419-40030-10 |
| MH-60R | 38403-40000-10 |
| S-70M | 71248-40020-10/ 71248-40030-10 |
| UH-1Y (customer part number 3239AS900-1) | - |
| ABE® Spare Part Pricing | |
| 115 VAC 60 HZ Cable | 40262-43014-10 |
| CA Assy SP Elec | 40262-43016-10 |
| Sys Controller Process Board | 40262-47033-10 |
| RU Cable | 40262-90040 |
| HHDU Cable | 40262-90041 |
| Power Cable | 40262-90049-1 |
| MU Cable | 40262-90058-1 |
| Hand Held Display Unit | 40262-95001 |

TEXTRON Systems

WWW.TEXTRONSYSTEMS.COM

| Product Name | Part Number |
|---|-------------|
| Measurement Unit Display | 40262-95002 |
| ABE® Repair Pricing | |
| ABE Minor Repair (Model 300, 310, 310A, 410A) | |
| ABE Major Repair (Model 300, 310, 310A, 410A) | |

TEXTRON Systems

WWW.TEXTRONSYSTEMS.COM

Quantity Discounts:

| Product Name | Part Number |
|--|-----------------|
| Synthetic Stimulus Instrument (SSI) Model Number VME SSI-50* | 40354-41110-50 |
| Qty 16-31 | |
| Qty 32-63 | |
| Qty 64-127 | |
| Qty 128+ | |
| Synthetic Stimulus Instrument (SSI) With MMW (-150) | 40491-40000-150 |
| Synthetic Stimulus Instrument (SSI) With MMW (-150) | 40491-42000-150 |
| Qty 16-31 | |
| Qty 32-63 | |
| Qty 64-127 | |
| Qty 128+ | |
| Synthetic Stimulus Instrument (SSI) With MMW (-151) | 40491-40000-151 |
| Synthetic Stimulus Instrument (SSI) With MMW (-151) | 40491-42000-151 |
| Qty 16-31 | |
| Qty 32-63 | |
| Qty 64-127 | |
| Qty 128 | |
| Synthetic Stimulus Instrument (SSI) Without MMW (-150) | 40491-41000-150 |
| Synthetic Stimulus Instrument (SSI) Without MMW (-150) | 40491-43000-150 |
| Qty 16-31 | |
| Qty 32-63 | |
| Qty 64-127 | |
| Qty 128+ | |
| Synthetic Stimulus Instrument (SSI) Without MMW (-151) | 40491-41000-151 |
| Synthetic Stimulus Instrument (SSI) Without MMW (-151) | 40491-43000-151 |
| Qty 16-31 | |
| Qty 32-63 | |
| Qty 64-127 | |
| Qty 128+ | |
| Stimulus Cabinet* | 40354-41105-50 |
| Qty 6-10 (3%) | |
| Qty 11 + (7%) | |
| Stimulus Cabinet* - 150 | 40354-41105-150 |
| Qty 6-10 (3%) | |
| Qty 11 + (7%) | |
| Maintenance/Alignment Receiver Cabinet* | 40354-41100-50 |
| Qty 6+ (3%) | |

TEXTRON Systems

WWW.TEXTRONSYSTEMS.COM

| Product Name | Part Number |
|--|-----------------|
| Maintenance/Alignment Receiver Cabinet* -150 | 40354-41100-150 |
| Qty 6+ (3%) | |
| Integrated EW Cabinet Assembly* (Used in our Single Cabinet EW Simulator, P/N 40354-40150-10) | 40354-40151-10 |
| Qty 6-10 (3%) | |
| Integrated EW Cabinet Assembly* -150 (Used in our Single Cabinet EW Simulator, P/N 40354-40150-110) | 40354-40151-110 |
| Qty 6-10 (3%) | |
| Integrated EW Cabinet Assembly* (Used in our Single Cabinet EW Simulator, P/N 40354-40150-20) | 40354-40151-20 |
| Qty 6-10 (3%) | |
| Integrated EW Cabinet Assembly* -150 (Used in our Single Cabinet EW Simulator, P/N 40354-40150-120) | 40354-40151-120 |
| Qty 6-10 (3%) | |
| Stimulation Electronics Assembly | 40537-41100-10 |
| Qty 1-3 | |
| Qty 4-7 | |
| Qty 8+ | |
| RF Switch Matrix | 40354-40500-10 |
| Qty 5-8 | |
| Qty 9-37 | |
| RF Switch Matrix -150 | 40354-40500-110 |
| Qty 5-8 | |
| Qty 9-37 | |
| A²PATS Upgrade Kits | |
| Stim Enclosure 4.4 Upgrade Kit | 78231-10014-10 |
| Qty 1-3 | |
| Qty 4-7 | |
| Qty 8+ | |
| Stim Cabinet 4.4 Upgrade Kit | 78231-10012-10 |
| Qty 1-2 | |
| Qty 3-5 | |
| Qty 6+ | |
| Maintenance Cabinet 4.4 Upgrade Kit | 78231-100111-10 |
| Qty 1-2 | |
| Qty 3+ | |
| Stim Cabinet MMW Upgrade Kit | 40537-40520-20 |
| Qty 1-2 | |
| Qty 3-5 | |

TEXTRON Systems

WWW.TEXTRONSYSTEMS.COM

| Product Name | Part Number |
|--|-----------------|
| | Qty 6+ |
| Maintenance Cabinet MMW Upgrade Kit | 40534-40201-20 |
| | Qty 1-2 |
| | Qty 3+ |
| Maintenance Enclosure MMW Kit | 78231-10013-10 |
| | Qty 1-2 |
| | Qty 3+ |
| Stim Cabinet -150 Power Upgrade Kit | 78231-10030-10 |
| | Qty 1-2 |
| | Qty 3-5 |
| | Qty 6+ |
| Maintenance Cabinet -150 Power Upgrade Kit | 40536-40510-410 |
| | Qty 1-2 |
| | Qty 3+ |
| A2 Desktop Signal Generator (A ² DSG) Upgrade Kit | |
| | Qty 1-2 |
| | Qty 3-5 |
| | Qty 6+ |
| RF SW/Freq Dist Unit (RFSU) | 154050-002 |
| | Qty 2 |
| | Qty 3-5 |
| | Qty 6-18 |
| RF SW/Freq Dist Unit (RFSU) | 152750-002 |
| | Qty 2 |
| | Qty 3-5 |
| | Qty 6-18 |
| Calibration Kit, Verification | 125670-002 |
| | Qty 2 |
| | Qty 3-5 |
| | Qty 6-18 |
| RFIU | 125610 |
| | Qty 2 |
| | Qty 3-5 |
| | Qty 6-18 |
| RFIU Enhanced | 125610--002 |
| | Qty 2 |
| | Qty 3-5 |
| | Qty 6-18 |

TEXTRON Systems

WWW.TEXTRONSYSTEMS.COM

| Product Name | | Part Number |
|--|-----------|----------------|
| Integrated Tester for Aircraft Survivability Systems (ITASS) | Qty 1-10 | 40514-40000-10 |
| | Qty 11-20 | |
| | Qty 21+ | |
| RF Module Assembly | Qty 1-14 | 40563-40020-10 |
| | 15-29 | |
| | 30-49 | |
| | 50+ | |
| Processor CCA | Qty 1-14 | 40568-47010-10 |
| | 15-29 | |
| | 30-49 | |
| | 50+ | |

| Product Name | Part Number |
|---|---------------|
| Barman 2 Software | EU00284-02-FG |
| UV Baringa 5.5 | EU00018-03-FG |
| Baringa™ 5.5 Kit 3 | EU00075-03-FG |
| Barman 3 Software | EU00284-03-FG |
| IR Baringa (2-Colour) | EU00035-02-FG |
| IR Barman Software (2-Colour) | EU00717-01-FG |
| MEON™ v3 | EU00101-03-FG |
| EMU Software | EU00152-04-FG |
| MEON v3 test set only | EU00101-03-04 |
| HCU Software (v3) | EU01264-03-FG |
| UV LED Mallina -180 | EU02173-01-FG |
| Very Heavy Duty Tripod System | EU02168-02-FG |
| Heavy Duty Tripod System | EU02168-01-FG |
| Medium Duty Tripod System | EU02176-01-FG |
| Carbon Fiber Tripod System | EU04580-01-FG |
| NEMESIS IR Beacon Mallina (IRM-16) | EU00048-02-FG |
| Mallina™ Laser Range Finder | EU00046-03-FG |
| Mallina Single Phase PSU | EU00388-02-FG |
| Mallina Battery Pack PSU | EU03400-01-FG |
| Mallina DVR | EU04064-01-FG |
| Mallina Data Logger (to be purchased with Mallina Event Logger) | EU03715-02-FG |
| Mallina Event Logger | EU04065-01-FG |
| GMSG-UV | EU00045-06-FG |
| GMSG-IR | EU03317-02-FG |
| GMSG-UV (inc MODTRAN) | EU04153-03-FG |
| GMSG IR (Inc. MODTRAN) | EU04450-02-FG |
| MalCom Software (inc Omni Drive) | EU00063-08-FG |
| Malcom Software | EU00060-08-FG |
| MSTS UD | EU04066-03-FG |
| MSTS UDL | EU04232-02-FG |
| MSTS UL | EU03755-03-FG |
| MSTS UI3L | EU04618-02-FG |
| MSTS UI3DL | EU04651-02-FG |

TEXTRON Systems

WWW.TEXTRONSYSTEMS.COM

| Product Name | Part Number |
|------------------------------|----------------|
| MSTS TPG | EU03165-06-FG |
| ITASS TPG | EU04764-06-FG |
| Red Phoenix Standard | EU00089-05-FG |
| Blue Phoenix Standard | EU00090-03-FG |
| Blue Phoenix Standard | EU00090-04-FG |
| Custom Alignment Kit | EU03995-02-FG |
| Stand Off Kit | EU04634-01-07 |
| Phantom™ Beamrider | EU03660-03-FG |
| Phantom TPG | EU04516-06-FG |
| Phantom L2 | EU05061-01-FG |
| Phantom LL2 | EU05123-01-FG |
| Griffen™ -50 | EU02156-01-FG |
| Griffen-50 (Ruggedized Case) | EU02156-01-FGR |
| GCU Software | EU02163-01-FG |
| Griffen Adapter | EU03244-01-FG |
| Thermal Sight | EU04063-04-FG |

Issue Date: January 2022

*ABE is a registered trademark of Textron Systems Corporation
A²PATS is a registered trademark of Textron Systems Corporation*